

Lewis & Wood

FABRIC CARE

All our fabrics follow the same care instructions



Do not wash




Do not bleach



Iron on medium temperature (max 300°F)



Dry clean only with any solvent other than Trichloroethylene



Do not tumble dry

Any questions email info@lewisandwood.com

www.lewisandwood.com